



1/30




FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C





FIG. 2D






FIG. 4




FIG. 5




FIG. 6




FIG. 7

CREATING A RECORD ON THE HANDHELD




FIG. 8A

12

1502

Client Data

Project 10/16/03 11:53:00 PM 1508

1503

Client Name 1504

Inspector 12

1505

Building Name 1506

Next

FIG. 8B

CLIENT DATA SCREEN INCLUDES NAME, TIME/DATE STAMP WITH GPS/GIS OR BARCODE WAND REPORT, TYPE OF DATA COLLECTION BEING PERFORMED DATE, INSPECTOR NAME, ETC.

12

1510

Geography

Barcode ID

1512

Room

Floor

1513

0

1514

Area Type

1515

Fire/CEB Rating

1516

1518

Delete Record

Previous Record

1518

First Record

Last Record

1518

FIG. 8C

GEOGRAPHY SCREEN PROMPTS CAPTURE OF BARCODE ID, ROOM AND FLOOR NUMBERS, AREA TYPE, TRANSDUCER READING, ETC.




FIG. 8D




FIG. 8E







FIG. 8G




DATA SUCH AS MEASUREMENTS OR FIELD CONDITIONS ARE COLLECTED BY MANUAL INPUT OR READ DIRECTLY INTO THE HANDHELD DEVICE TEMPLATE UTILIZING A MEASURING DEVICE CONNECTED DIRECTLY INTO THE UNIT.

FIG. 8H




THE GREEN DIAGRAM BUTTON SHOWN IN THE PREVIOUS SLIDE BRINGS YOU TO A SKETCH SCREEN FOR INPUT OF A SKETCH DIRECTLY INTO THE RECORD AT A TIME OF CAPTURE.

FIG. 8I



THE PHOTO INTEGRATION SCREEN PROMPTS THE OPERATOR TO TOGGLE OVER TO THE BUILT IN CAMERA AND COLLECT A PHOTO OF THE ITEM TO BE INSERTED INTO THE RECORD AT TIME OF CAPTURE.

FIG. 8J

**FIG. 8K**

THE PHOTO IS CAPTURED, ACCEPTED, SELECTED AND INSERTED DIRECTLY INTO THE RECORD.




FIG. 8L

SCREEN TAP INSERTS PHOTO(S) INTO RECORD

1560

Tubing

Types Lab Service ▼ ☐ Bundled?

Diameter of Tubing 1 1/2" ▼

of Bundle 1 1/2" ▲

Constructi 2" ▤

2"1/2" ▼


3" ▼

Special Conditions ▼

Annular Minimum Annular Maximum

FIG. 8M

ADDITIONAL DATA IS COLLECTED AND RECORDED AS REQUIRED.

**FIG. 8N**

SIGNATURE IS COLLECTED AND INSERTED DIRECTLY INTO THE RECORD AT TIME OF CAPTURE

SCREEN MOVES OPERATOR TO NEXT RECORD, NEW CLIENT OR TO CLOSE INSPECTION.




FIG. 80




FIG. 8P

ISSUES BY ROOM

Kluso Solutions Inc.

Client	Building	Floor	Room
Anheiser-Busch, Inc.	Power Plant	9	1

Barcode 1234

FireStop Issue	Issue Type	Size	Min	Max	Materials	Construction System	Special Conditions
Floor Penetration	Duct	2'	1'	1'	Aluminum	Brick	Eccentric
Floor Penetration	Duct	2'	1'	1'	Aluminum	Brick	Eccentric

Client	Building	Floor	Room
ASI Management	Power Plant	6	0

Barcode

FireStop Issue	Issue Type	Size	Min	Max	Materials	Construction System	Special Conditions
Floor Penetration	Cable/Bundle/Tray			1'	Aluminum	Brick	

Client	Building	Floor	Room
GSA	Power Plant	0	0

Barcode

FireStop Issue	Issue Type	Size	Min	Max	Materials	Construction System	Special Conditions
Floor Penetration	Duct			1'	Aluminum	Brick	

Friday, September 16, 2001

Page 1 of 1

Summary
Report

FIG. 9B



Work Order Number : 134-90-B54

Repair Order

Date 10/13/03

Client Information:

Client **Anheuser Busch, Inc** Location **Newark Brewery**
 Address **100 Rt 1&9, Newark, NJ 07070** Building Number **4** Room Number **437A** Print Number **6-76y**

Issue Information:

Type **Through Penetration** Trade Required **Fire Stop Contractor**
 Description **Copper pipe through cmu block wall, 2 hour rated in entry area of room.**
 Priority **HIGH** UL System Selected **UL# CAJ-4501-A** Special Instructions **This is a Safety Issue**

Producers Signatur


Approval Signature

Assignment of Work:

Contractor Assigned **Ace Construction Inc**☐ Provide Estimate for Approval☒ Time and Materials WorkContact Name **Joe Sims**☒ Estimated Cost \$ **600.00**Telephone Number **732-528-0473**

This work is included in our existing contract with the assigned contractor and must be completed at no additional cost to the existin contract for services.

Deficiency Digital Photo



Open Space

Approvals and Inspections

☒ Work inspected and approved

Signature

10/13/03

Date

Time and Date: 10/20/2003 12:06:13 PM

FIG. 10

FIRE BARRIER REPORT

CLIENT PROJECT	ASI MANAGEMENT SCOPE OF SERVICES	INSPECTION DATE/TIME	10/10/2003 9:15:00 AM
		INSPECTOR NAME	VAL O'CONNOR
BUILDING	POWER PLANT	FLOOR	2
		ROOM	14
		AREA TYPE	ELECTRICAL ROOM
FIRE STOP ISSUE	FIRE RATING	ISSUE TYPE	
WALL PENETRATION	2 HOUR	PIPE:	
DIMENSIONS	CONSTRUCTION SYSTEM	ANNULAR MAX	ANNULAR MIN
5"	BLOCK	1 1/2"	1/2"
MULTI ISSUES			
DEFECTS			
		UTILITY	MATERIALS
		VENT	ALUMINUM
		INSULATION	SPECIAL CONDITIONS
		FIBERGLASS 1/2"	ECCENTRIC
		BARCODE	
		T-3158621.456	


I CERTIFY THAT I AM AN INDEPENDENT INSPECTOR AND REPRESENT FIRESTOP INSPECTOR LLC. IN ACCORDANCE WITH ASTM 2174, I AM NOT AFFILIATED WITH ANY CONTRACTOR, SUPPLIER, MANUFACTURER OR DISTRIBUTOR OF FIRE STOP OR PASSIVE FIRE PROTECTION PRODUCTS.

SIGNATURE

Val O'Connor

REPAIR RECOMMENDED

PHOTO



DIAGRAM




FIG. 11





FIG. 12






FIG. 14